

Oil Field Environmental Incident Summary

Incident: 20150317214142 **Date/Time of Notice:** 03/17/2015 21:41

Responsible Party: Missouri Basin Well Service Inc

Well Operator: MISSOURI BASIN WELL SERVICE, INC.

Well Name: Hystad 1 SWD

Field Name: POE

Well File #: 8977

Date Incident: 3/17/2015

Time Incident: 10:00

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 100

Sec: 2

Qtr:

Location Description:

Submitted By: Joshua Staggs

Received By:

Contact Person: Dave Wanner
12983 35th St SW
Belfield, ND 58622

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	60	Barrels	40	Barrels	60	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/7/2015

Clean Up Concluded: 4/3/2015

Risk Evaluation:

None, the spill was contained within the dike.

Areal Extent:

Potential Environmental Impacts:

None, the spill was contained within the dike.

Action Taken or Planned:

Repair of computer system after the contractor pinpoints the problem.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 3/18/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank overflow, remained on location within the diking according to the report. NDIC retains oversight.